



## FIELD NOTICE

**Date:** December 11, 2014

**Field Notice Number:** 327-L14

**Models or Product Affected:** Dometic, Cruisair & Marine Air Systems

**Recipients:** Dealers, Master Dealers, Distributors, OEMs, Manufacturer's Reps

### Changes To Cleaning Condenser Coils

Dometic is studying various chemicals in an effort to provide the best guidance for proper cleaning of condensers.

During our study, we have found that Muriatic and other uninhibited Hydrochloric Acid based products are among the harshest chemicals and significantly reduce the wall thickness of the CuNi tube in a short period of time. Therefore, Dometic has removed the use of these from the maintenance sections of our operation manuals.

Any further use of Muriatic and other uninhibited Hydrochloric Acid based products will be at the risk of the user.

In the near future we will be publishing recommended cleaners as a result of our study.

#### Dometic Marine Headquarters

2000 N. Andrews Ave. Ext. • Pompano Beach, FL 33069-1497 USA • Phone: 954-973-2477 • Fax: 954-979-4414 • [www.DometicUSA.com](http://www.DometicUSA.com)  
ISO 9001:2008

